



November 8, 2013

## **ATTACHMENT A PROJECT UPDATE**

The following is an update on the most recently completed emission reduction projects listed on Attachment A to the ESCO Good Neighbor Agreement (GNA).

### **PROJECT #10: Take corrective action to reduce fugitives on thermal sand reclaimer baghouse by installing coarse fraction separator to improve collection and reduce wear on baghouse.**

**Actions and Status:** ESCO added a cyclone separator in January 2011, which experienced high wear and a portion of which was replaced in June 2012. This new section again started to wear and was replaced in July 2013 with a ceramic tile-lined cyclone section that is expected to last much longer than previous installations.

**Results:** Reductions in Particulate Matter (PM)

**Method of Confirmation:** ESCO will inspect baghouse monthly and take corrective action as needed. ESCO will maintain records of monthly inspections and corrective action.

ESCO inspects the baghouse and coarse fraction separator at least monthly and takes corrective action as needed. Records of inspections and corrective actions are maintained.

---